

LUFTFARTSVERKET  
Hovedadministrasjonen  
Luftfartsinspeksjonen  
Postboks 8124 Dep., 0032 Oslo  
Telefon : 22 94 20 00  
Telefax : 22 94 23 91  
Tigr. : CIVILAIR  
Telex : 71032 enfb n

# LUFTDYKTIGHETSPÅBUD (LDP)

TILBEHØR

AIR LIQUIDE - 1

---

Med hjemmel i lov av 11. juni 1993 nr. 101 om luftfart, kap. XV § 15-4 jf. kap. IV § 4-1 og Samferdselsdepartementets bemyndigelse av 25. mars 1994, fastsetter Luftfartsverket følgende forskrift om luftdyktighet.

---

## 97-044 UTSKIFTING AV «SMOKE HOODS»

### Påbudet gjelder:

Air Liquide Smoke Hoods type 15-40 F som har produksjonsserier (lots) som listet i vedlagte kopi av DGAC AD 97-088(AB)R1.

### Påbudet omfatter:

Utfør tiltak som beskrevet i vedlagte kopi av DGAC AD 97-088(AB)R1.

### Tid for utførelse:

Til de tider som beskrevet i vedlagte kopi av DGAC AD 97-088(AB)R1, med virkning fra denne LDP's gyldighetsdato.

### Referanse:

DGAC AD 97-088(AB)R1

### Gyldighetsdato:

01.07.97.

G S A C

**AIRWORTHINESS DIRECTIVE**

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this**Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive*

Translation of 'Consigne de Navigabilité'

ref.: 97-088(AB)R1

In case of any difficulty, reference should  
be made to the French original issue.**AIR LIQUIDE****Smoke hood type 15-40 F**

Visors

This Airworthiness Directive applies to smoke hoods manufactured by AIR LIQUIDE type 15-40 F. They can be installed on any type on aircraft. The concerned lots are :

Lot n° :	8141	8473	8569	8744	9003
	8283	8474	8570	8801	9007
	8359	8475	8656	8840	9254
	8389	8477	8657	8841	
	8413	8524	8682	8842	

It has been discovered that some visors become blind (white) within the minutes following the opening of the vacuum package. In order to eliminate the potential risk presented by these hoods, the following measures are rendered mandatory on the effective date of this Airworthiness Directive :

1. Within the fifteen next days, checks the serial number of the hoods belonging of these lots and installed on the aircraft. These information will be transfer to AIR LIQUIDE, which address is given below :

AIR LIQUIDE/DTA  
BP 15

38360 SASSENAGE (FRANCE)

Tel : 33 (0)4.76.43.60.60

Fax : 33 (0)4.76.43.60.98

Telex : ALSAS 320825F

Email : richard.zapata@ air liquide.com

2. Within the next six months all concerned hoods will have to be removed.

.../...

March 26, 1997

AIR LIQUIDE  
Smoke hoods type 15-40 F

97-088(AB)R1

GSAC

AIRWORTHINESS DIRECTIVE ref.: 97-088(AB)R1

Page n° 2

3. The installation on aircraft of hoods belonging the above lots is prohibited.

Note : Smoke hoods identified with a R1 marked on the label, belonging to any lots, are not concerned by this Airworthiness Directive.

---

Ref. : AIR LIQUIDE Alert Service Letter  
N° 25-001 Rev. 1 dated March 10, 1997

---

The original issue of this Airworthiness Directive has been only subject of a telegraphic diffusion on March 07, 1997.

This Revision 1 has been subject of a telegraphic diffusion on March 10, 1997.

---

EFFECTIVE DATE : MARCH 20, 1997

**BLANK**