

Luftfartstilsynet
1. tilsynsavdeling
Postboks 8050 Dep., 0031 Oslo
Besøksadresse:
Rådhusgata 2, 0031 Oslo
Telefon : 23 31 78 00
Telefax : 23 31 79 95
e-post: postmottak@caa.dep.no

TILBEHØR

LUFTDYKTIGHETSPÅBUD (LDP)

INNOVINT -1

Med hjemmel i lov av 11. juni 1993 nr. 101 om luftfart, kap. XV § 15-4 jf. kap. IV § 4-1 og Samferdselsdepartementets bemyndigelse av 25. mars 1994, fastsetter Luftfartstilsynet følgende forskrift om luftdyktighet.

2001-048 MODIFIKASJON AV INNOVINT BASSINET

Påbudet gjelder:

Britax Sell GmbH & Co OHG Galley utstyr som beskrevet i vedlagte kopi av LBA AD 2001-351(B).

Påbudet omfatter:

Utfør tiltak som beskrevet i vedlagte kopi av LBA AD 2001-351(B).

Tid for utførelse:

Til de tider som beskrevet i vedlagte kopi av LBA AD 2001-351(B), med virkning fra denne LDP's gyldighetsdato.

Referanse:

LBA AD 2001-351(B).

Gyldighetsdato:

2001-09-03.

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité' ref. : 2001-351(B)
In case of any difficulty, reference should be made to the French original issue.

INNOVINT AIRCRAFT INTERIOR

Equipment: babies bassinets

PIP pins protection flap assy installation and installation of a set screw (ATA 25)

1. APPLICABILITY:

INNOVINT AIRCRAFT INTERIORS baby bassinets model basic PNR : 7250-XXA, 7250-XXB, 7253-XXB, all serial numbers.

These baby bassinets can be installed, but not limited to, AIRBUS, BOEING, DOUGLAS and FOKKER aircraft.

2. REASON:

Due to unprotected PIP-pin, Innovint baby bassinets can be unintentionally released by passengers or attendants and fall to the cabin floor. This situation, if left uncorrected, can lead to serious injury to baby during the fall.

3. COMPLIANCE:

Before December 31, 2002, to prevent the PIP-pin against inadvertent release, modify pin installation as per Service Bulletin INNOVINT AIRCRAFT INTERIOR 7250-25-002 and Service Bulletin INNOVINT AIRCRAFT INTERIOR 7250-25-003.

REF.: Service Bulletin INNOVINT AIRCRAFT INTERIOR 7250-25-002
Service Bulletin INNOVINT AIRCRAFT INTERIOR 7250-25-003

EFFECTIVE DATE : AUGUST 18, 2001

August 08, 2001

INNOVINT AIRCRAFT INTERIOR
Equipments: Babies bassinets

2001-351(B)