

Luftfartstilsynet  
Postboks 8050 Dep., 0031 Oslo  
Besøksadresse:  
Rådhusgata 2, Oslo  
Telefon : 23 31 78 00  
Telefax : 23 31 79 95  
e-post: postmottak@caa.dep.no

# LUFTDYKTIGHETSPÅBUD (LDP)

TILBEHØR

SUN PATH  
PRODUCTS - 001

---

Med hjemmel i lov av 11. juni 1993 nr. 101 om luftfart, § 15-4 jf. § 4-1 og det vedtak om delegering av myndighet til Luftfartstilsynet av 10. desember 1999 nr. 1273

## 2004-024 "ADJUSTABLE MAIN LIFT WEB HARNESS"

### Påbudet gjelder:

Web harness på Javelin and Odyssey harness/container system som beskrevet i vedlagte kopi av DGAC AD F-2004-027.

### Påbudet omfatter:

Tiltak skal utføres som beskrevet i vedlagte kopi av DGAC AD F-2004-027.

### Tid for utførelse:


Til de tider som er beskrevet i vedlagte kopi av DGAC AD F-2004-027.

### Referanse:

DGAC AD F-2004-027.

### Gyldighetsdato:

2004-04-13.

	<b>AIRWORTHINESS DIRECTIVE</b> <b>No F-2004-027</b>	Distribution: <b>A</b>	Issue date: <b>February 18, 2004</b>	Page : <b>1/2</b>
	Direction générale de l'aviation civile France  GSAC publication	This Airworthiness Directive is published by the DGAC : <input checked="" type="checkbox"/> on behalf of EASA, the Primary Airworthiness Authority for the affected product. <input type="checkbox"/> as the Registration Airworthiness Authority for the affected aircraft..		<i>Translation of « Consigne de Navigabilité » of same number.          In case of difficulty, reference should be made to the French issue.</i>
<b>No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive, unless otherwise agreed with the Authority of the State of Registry.</b>				
Corresponding foreign Airworthiness Directive(s): <b>Not applicable</b>		Airworthiness Directive(s) replaced: <b>None</b>		
Person in charge of airworthiness: <b>SUN PATH PRODUCTS, INC.</b>		Type(s): <b>Harnesses and containers</b>		
Type certificate(s) No. <b>None</b> TCDS No <b>None</b>				
ATA chapter: <b>25</b>	Subject: <b>Equipment - Adjustable main lift web harness</b>			

**1. EFFECTIVITY:**

All adjustable main lift web harness on Javelin and Odyssey harness/container system.

**2. REASONS:**

An investigation is going on to identify the root cause of an accident that occurred after the failure of a Student Javelin harness/container Main Lift Web (MLW).

A shearing through its securing webbing has been observed. Such a shearing may lead to a fatality.

**3. MANDATORY ACTION AND COMPLIANCE TIME:**

Upon receipt of this Airworthiness Directive (AD), from February 18, 2004, apply SUN PATH PRODUCTS, INC. Service Bulletin (SB) SP02, inspect the webbing securing the adjuster in place at the junction of the legstrap and lateral side supports for wear or tear.


As a preventive measure, and pending investigation final results, ground the harnesses concerned because of wear or tear.

**4. REFERENCE PUBLICATION:**

SUN PATH PRODUCTS, INC. Service Bulletin SP02 dated July 22, 2003.

**5. EFFECTIVE DATE:**

Upon receipt from February 18, 2004.

	<b>AIRWORTHINESS DIRECTIVE</b> <b>No F-2004-027</b>	Distribution: <b>A</b>	Issue date: <b>February 18, 2004</b>	Page: <b>2/2</b>
---	--	---------------------------	---	---------------------

**6. REMARK:**

For questions concerning the technical contents of this AD's requirements, contact:

SUN PATH PRODUCTS, INC.  
4439 Skydive Lane  
ZEPHYRHILLS, FL 33542 USA  
Phone number: 1 (813) 782 9242  
Fax number: 1 (813) 788 3057

**7. APPROVAL:**

This AD is approved under EASA reference No 2004-1044 dated February 10, 2004.

**BLANK**