

Luftfartstilsynet
Postboks 8050 Dep., 0031 Oslo
Besøksadresse:
Rådhusgata 2, 0031 Oslo
Telefon : 23 31 78 00
Telefax : 23 31 79 95
e-post: postmottak@caa.dep.no

LUFTDYKTIGHETSPÅBUD (LDP)

TILBEHØR

MarS a.s - 1
(Tidl. MarS spol s.r.o)

Med hjemmel i lov av 11. juni 1993 nr. 101 om luftfart, kap. XV § 15-4 jf. kap. IV § 4-1 og Samferdselsdepartementets bemyndigelse av 25. mars 1994, fastsetter Luftfartstilsynet følgende forskrift om luftdyktighet.

2002-033B REDNINGSFALLSKJERMER

Påbudet gjelder:

MarS a.s. redningsfallskjerner som beskrevet i Tsjekkisk CAA-AD-T-039/2002R2

Påbudet omfatter:

Utfør tiltak som beskrevet i vedlagte kopi av Tsjekkisk CAA-AD-T-039/2002R2.

Tid for utførelse:

Til de tider som beskrevet i vedlagte kopi av Tsjekkisk CAA-AD-T-039/2002R2.

Referanse:

Tsjekkisk CAA-AD-T-039/2002R2.

Gyldighetsdato:

2003-08-18.

CAA

CIVIL AVIATION AUTHORITY
CZECH REPUBLIC
Airworthiness Division

*Airport Ruzyne, 160 08 Prague 6
Tel: 420 233320922, fax: 420 220562270*

AIRWORTHINESS DIRECTIVE

Number: CAA-AD-T-039/2002R2

Supersedes CAA-AD-T-039/2002R1

Date of issue: July 1, 2003

MarS a.s. (formerly MarS spol. s.r.o.)
ATL-88, ATL-88/92-S, ATL-88/90

APPLIANCE – RESCUE PARACHUTE – EXCLUSION FROM OPERATION

Applicability: Rescue parachutes ATL-88, ATL-88/92-S, ATL-88/90, produced by MarS spol s.r.o. between December 30, 1997 and February 11, 2003 incl., on which Mandatory Service Bulletin No.: 1/04/2002 has not been accomplished.

Reason: Since December 30, 1997 producer MarS spol s.r.o. has not a valid Approval Certificate for Production according to § 17 of Czech Aviation Act No.: 49/1997 Col. and producer continued in production and release to service after this date without Approval Certificate. From this reason all rescue parachutes ATL-88, ATL-88/92-S, ATL-88/90 produced between December 30, 1997 and February 11, 2003 incl. are unairworthy for operation in civil aviation.


Since May 7, 2002 producer MarS a.s. has Approval Certificate for maintenance for rescue parachutes ATL-88, ATL-88/92-S, ATL-88/90. After accomplishing of Mandatory Service Bulletin No.: 1/04/2002, with result "Airworthy", are above mentioned rescue parachutes airworthy for operation in civil aviation.

Since February 12, 2003 producer MarS a.s. has Production Organisation Approval according to JAR 21 Subpart G. For this reason is this AD applicable for rescue parachutes produced between December 30, 1997 and February 11, 2003 incl. only.

Effective date: Upon receipt.

Compliance: Upon receipt of this AD hand over (after agreement with MarS a.s.) all rescue parachutes ATL-88, ATL-88/92-S, ATL-88/90 produced by MarS spol s.r.o. (now MarS a.s., Okružní II. č.p. 239, 569 43 Jevíčko, Czech Republic, Phone: +420 462 327 816, Fax: +420 462 327 837) between December 30, 1997 and February 11, 2003 incl. for inspection and for accomplishing of Mandatory Service Bulletin No.: 1/04/2002.

Remarks: Where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport, 160 08 Prague 6, Czech Republic, tel: 420 233320922, fax: 420 220562270.


Ing. Pavel MATOUŠEK
Director